


T. 135 R. 32 M. 5th Coordinates: X _____ Y _____
N 1/4 14 Corner common to sections 11, 14



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1866
Original monument POST

Species	Bearing	Trees
<u>ASPEN</u>	<u>ASPEN</u>	
Diameter <u>14"</u>	<u>14"</u>	
Bearing <u>S 25 E</u>	<u>N 5 1/2 W</u>	
Distance <u>5 LKS</u>	<u>50 LKS.</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1916 By E. B. HORST
Location filed County Book 'B' P. 51
Monument SET 1 1/2 x 48" I.M.
also on microfilm - roll 115 BK 71 P. 133

Evidence of Subsequent Corner Restoration

Year of search 1985 8/26 By Terry Freeman
find I.M. bent badly, down 0.3'
in line w/ fence 5'
more digging needed.
1986 - 8/13 found 1/2 x 12" box under bent I.P.
replaced w/ cast iron monument - iron bar reset on N. side

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Burr Oak</u>	<u>8"</u>	<u>N 90 E</u>	<u>42.66'</u>
<u>Burr Oak</u>	<u>10"</u>	<u>N 49 E</u>	<u>44.87'</u>
<u>CFP</u>		<u>S 20 W</u>	<u>34.78'</u>

1987-Curo - Certificate - Doc # 297496

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Walt Curo - 1987
(see other side)

2000 - CCSO

Find in place 4" CIM dwn, 0.4'
located @ C.R. 156, fence line N/S, and
33' ± E of E field ent.

REF. TIES:

<u>(find) 7" W. Oak</u>	<u>N 90 E</u>	<u>42.67'</u>
<u>11" W. Oak</u>	<u>N 49 E</u>	<u>44.52'</u>
<u>P. Pole</u>	<u>S 52 E</u>	<u>57.73' (TAG)</u>
<u>(find) CFP</u>	<u>S 20 W</u>	<u>34.98'</u>

* distance to dbl. hd. nail