


T. 135 R. 32 M. 5TH Coordinates: X _____ Y _____
N 1/4 22 Corner common to sections 15, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1866
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>BL. PINE</u>	<u>BL. PINE</u>	
Diameter	<u>20"</u>	<u>18"</u>	
Bearing	<u>S 18 W</u>	<u>N 24 1/2 W</u>	
Distance	<u>52 LKS</u>	<u>44 LKS</u>	

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By E. B. Hoest
Location filed COUNTY BOOK "C" P. 47
Monument SET 50d SPIKE SET 1/2 x 48" T.M.
d 150 on microfilm - roll 115 BK 71 P. 126-127
1915 - Bryant - microfilm - roll 115 BK 71 P. 86

Evidence of Subsequent Corner Restoration

Year of search 5/2000 By DNR
Found 1 1/4" IP on E Gravel road.
Cert of Location Doc. #434531

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Fence Post</u>	<u>P. Pole</u>	_____	_____
<u>N 15° W</u>	<u>S 10° W</u>	_____	_____
<u>34.76</u>	<u>32.78</u>	_____	_____
<u>DNR RP</u>	<u>DNR RP</u>	_____	_____

N-15

Subsequent Corner Restoration

Year surveyed 3/2001 By CCSO
Location filed P. 1c #2001.023
Monument Found 1 1/2" ODIP, down 0.1,
2' ± N. of & CR #30, 9' ± E. of fence
line North, 2000 DNR witnesses
good, add the following:

5" J. Pine N 22° E, 35.58' *
3" J. Pine S 61° E, 68.16' *
* distance to double head nail

- Corner GPS 11/5/02 CCSO
1 1/2" ODIP, down 0.2, 2' ± N. of #30

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____