


T. 135 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 25 Corner common to sections 24, 25 and 19, 30-135-31



EXISTING SURVEYS

Original Government Survey
Year surveyed 1858
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>
Diameter	<u>12"</u>	<u>9"</u>	<u>8"</u>
Bearing	<u>S55 1/4 W</u>	<u>N45 W</u>	<u>N71 1/4 E</u>
Distance	<u>38 LKS.</u>	<u>30 LKS.</u>	<u>27 LKS.</u>

Original Bearing Trees Found

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1941 By State Hwy Dept.
 Location filed Road plans for State Hwy #64
 Monument assumed corner at intersection of roads
is 41.5' W. of new centerline

Evidence of Subsequent Corner Restoration

Year of search 8/26/86 By Terry Freeman
Set cast iron monument from Hwy Plans
41.5' W. of C, down 0.3'

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

P.P.	Bearing	Distance	Reference Objects
	<u>N43°W</u>	<u>48.35'</u>	<u>CFP</u>
	<u>S77°W</u>	<u>52.00'</u>	<u>Tele junct box</u>
	<u>S74°E</u>	<u>118.55'</u>	

Corner Certificate - Curro - 1987 Doc #297503

R-25

Subsequent Corner Restoration

Year surveyed 5/2001 By CCSO
 Location filed CCSO
 Monument Found base of CIM, down
1.0' on E of 88th St. and 41 1/2 W of Hwy
#64. Also 1986 witness NW, add the
following:

"X" on Steel Plate on 48" RCP N38°E,
97.12'
PK nail on 18" CMP, S78°E, 80.98'
Tele Red Post S33°W, 41.70' dbl. hd. nail

- Corner GPS 10/14/02 CCSO
Clon, top gone, down 0.2, 44' ± W. of
Hwy #64, 2' ± N. of 88th St.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Walt Curro - 1987
Dec. 1900; Twp rd order shows no survey