


T. 135 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 R 6 Corner common to sections 25, 26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1866  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	Bearing	Trees
<u>BL. PINE</u>	<u>BL. PINE</u>	
Diameter <u>6"</u>	<u>6"</u>	
Bearing <u>S68 1/2 E</u>	<u>N78 E</u>	
Distance <u>49 LKS.</u>	<u>56 LKS.</u>	

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1985 9/16 By Termy Freeman  
Dug w/ backhoe in area of N-S Rd and fences E-W  
Dug 10' N-S X 8' E-W X 3' deep. 6" sand top, 1.5'  
fill, dug 1' into gray-silty loam - found nothing

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Jack Pine</u>	<u>Jack Pine</u>	<u>Birch</u>
<u>10"</u>	<u>6"</u>	<u>4"</u>
<u>558° W</u>	<u>533° W</u>	<u>530° E</u>
<u>45.40'</u>	<u>50.96'</u>	<u>32.70'</u>

Corner Certificate - Curo - 1987 - Doc # 297504

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Walt Curo - 1987  
May 1902; Twp rd order shows no survey