


T. 136 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 17 Corner common to sections 8, 9, 16, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument Post

Species	Bearing	Trees	
<u>B. PINE</u>	<u>B. PINE</u>	<u>B. PINE</u>	<u>B. PINE</u>
Diameter <u>6"</u>	<u>6"</u>	<u>7"</u>	<u>7"</u>
Bearing <u>S8E</u>	<u>N45E</u>	<u>N57W</u>	<u>S72W</u>
Distance <u>14 LKS</u>	<u>25 LKS</u>	<u>70 LKS</u>	<u>62 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1913 By HARRY TODD

Location filed COUNTY SURVEY RECORD BOOK B' P. 309

Monument FIND OLD GOVT B.T'S: DOWN 6" B.L. PINE
N45E 25 LKS, AND STUMPS OF OTHER 3 TREES
SET 2x48" GALV. I.P.
1918, J.H. FLYNN, COUNTY RESURVEY 'E-22' 2 1/2x48" I.P.

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1918 By J.H. FLYNN

COUNTY BOOK 'C' P. 138 FND I.P.M.

1917 - E.B. Horst - microfilm - roll 105 BK 64 P. 76-77
Found corner

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

J-9 Subsequent Corner Restoration

Year surveyed 1978 By Landecker Assoc

Location filed _____

Monument Found iron monument while
doing boundaries of Miller Shores
@ Pineview North.

10/01 - WSN found 2 1/2" iron
pipe, 1' below grade at intersection
determined to be H. Todd 1913
position.

12/03 - WSN set Cotton Gin pin
over iron monument and witness

P. Pole NE 42.35 to PK
6" Pine SE 59.48 to Nail
Fence cor SW 42.37 to PK
A Cop L was filed.

March 2004 B. Grivna # 17253
(cert. of Sur. Shows mon. found)

August 1905 W.H. Luffman
Trap Road order shows survey

Evidence of Subsequent Corner Restoration Found

Year of search 5-13-04 By B. Grivna # 17253

CCRO # A000488019 Second Cert. of Location
2" iron pipe bent SE, cly down 1.1'

Power Pole	Corner Final Post	Tree(?)
<u>N 30° E</u>	<u>S 40° W</u>	<u>S 30° E</u>
<u>42.40'</u>	<u>42.40'</u>	<u>59.25'</u>
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Remonumentation certificate prepared # 479 091

By # 16102
Date 1/16/04

Filed at CCRO