


T. 136 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 9 Corner common to sections 3, 4, 9, 10 W.C. 2.75 CH. SOUTH



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
 Original monument W.C. POST

Original Evidence Found

Year of search 1905 By Hicks
 Monument found WC 275 lks South

	Bearing Trees	
	<u>J.P. NE</u>	<u>J.P. NE</u>
Species		
Diameter	<u>10"</u>	<u>10"</u>
Bearing	<u>S 25 E</u>	<u>R 2 1/2 W</u>
Distance	<u>37 lks</u>	<u>24 lks.</u>

Original Bearing Trees Found

Species	<u>W.P.</u>	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1913 By John Curo
 Location filed County Survey Record Book B" P. 17-28
 Monument END W.C. B.T. 10" Pine S 25 E 37 lks.
SET HUB. SET HUB & TACK FOR TRUE NE 9
SET 2 1/2 X 48" GALV I.P. IN CONCRETE

Evidence of Subsequent Corner Restoration

Year of search Dec 2002 By CCSO
Found 2 1/2" OD IP w/plumber cap, 0.1'
below water, 118" ± into pond, 33' ± S.
of fence line. On old rd grade.

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Bearing Trees, Reference Objects

<u>Boulder</u>	<u>Maple Clump</u>
<u>6' x 4' x 3'</u>	<u>6"</u>
<u>N 10° W</u>	<u>S 89° W</u>
<u>70.10'</u>	<u>152.23'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
