


T. 136 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 21 Corner common to sections 15, 16, 21, 22



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument POST

Species	Bearing	Trees	
<u>TAM</u>	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>
<u>10"</u>	<u>8"</u>	<u>6"</u>	<u>12"</u>
<u>N76W</u>	<u>N50E</u>	<u>S65W</u>	<u>S54E 22LKS.</u>
<u>10 LKS</u>	<u>5LKS</u>	<u>4LKS</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

O = Corner

Subsequent Corner Restoration
 Year surveyed 1913 By JOHN CURO
 Location filed COUNTY SURVEY RECORD BOOK "B" P. 12-28
 Monument Find old Govt B.T. Done: 10" TAM N76W
10 LKS, 12" TAM S54 E 14.52' SET 3X3X15" HUB
SET 2 1/2 X 48" GALV. IIP. IN CONCRETE
1922, HURST, BOOK "D" P. 184 Find I.M.

Evidence of Subsequent Corner Restoration
 Year of search 1986 By Dave Landecker
 Corner Certificate - Doc # 297692
Find NW B.T from 1922 - I.P. N 45W 46.7'
Set cast iron monument

Bearing Trees, Reference Objects
 Species I.M. I.M.
 Diameter 1 1/4 x 30" 1 1/4 x 30"
 Bearing N45E N45W
 Distance 46.7' 46.7'
1922 TIES

Bearing Trees, Reference Objects
 I.P. Norway Pine Ash Balsam
10" TWIN 8" 8"
N45W N32E N85E S52E
46.7' 92.0' 48.73' 37.21'

N-13

Subsequent Corner Restoration
 Year surveyed 5/99 By CCSO
 Location filed CCSO
 Monument 11M down 0.5' in 4 Cor. #25
20'± South of fence line to West.

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
Certificate - Dave Landecker - 1986
Doc # 297692

- 13" N. Pine, N32°E, 92.00' *
- 12" Twin Ash, N85°E, 48.73' *
- 11" Balsam, S52°E, 37.21' *
- Survey Marker East, 32.0'

* distance to 20d spike
-Corner GPS 10/10/02 CCSO
Spk/washer from ties