

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R5

CASS COUNTY LAND CORNER RECORD

T. 136 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey
Year surveyed 1870
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	TAM.	TAM.	TAM.	TAM.
Diameter	7"	8"	6"	9"
Bearing	N40E	N49 1/2 W	S18E	S21W
Distance	12 LKS	8 LKS	10 LKS	28 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1916 By JOHN CURD
Location filed COUNTY SURVEY RECORD BOOK 8 P. 247-257
Monument Five Post SET By HALLETT - CHECKS w/ 2 OLD B.T. STUMPS.
1916 - JOHN CURD BOOK 8 P. 255-257 SET WAGON SPOKE PROPORTIONALLY 4 STAKES "R.P.S." NE, NW, SE, SW 46.70'.

Evidence of Subsequent Corner Restoration
Year of search _____ By _____
← 1916 - also on microf. film - roll 105 BK 67 P. 8-9
← also on microf. film - roll 105 BK 67 P. 38

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

R-5

Subsequent Corner Restoration
Year surveyed 1998 By Landecker & Assoc
Location filed Walker office
Monument Certificate of survey indicates monument found.

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

5/99 CCSO crew found capped 1/2" IP PLS #17008, 34' ± South of & Co. Rd. #24 and witnessed:
6" Willow, S16°E, 106.16 dbl. hd. nail Capped IP, South, 67.13
"X" N. end 24" Conc. Cul., N30°E, 86.01'
"X" S. end 24" Conc. Cul., S80°E, 45.60'
- Corner GPS 10/10/02
7/8" ODIP, PLS 17008, 34' ± S. of #24

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____