


T. 136 R. 32 M. 5th Coordinates: X _____ Y _____

NE 27 Corner common to sections 22, 23, 26, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1866
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	Tamarack	Tamarack	Spruce	Spruce
Diameter	18"	16"	5"	4"
Bearing	N 26° E	S 11° W	S 46° E	N 52° W
Distance	10 links	23 links	14 links	36 links

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1957 By MN/DOT
Location filed: S.P. 1109 (T.H.64=193) File 15-56-009
Monument:
Sec. Cor. at Int. N. S. Rd. & Fe. W. at P.O.T. Station 938+15.6

Evidence of Subsequent Corner Restoration

Year of search 7/2000 By CCHD/SO
Location filed: #2000.050
Monument: Found 3/4" iron pin
down 0.7', on centerline of State Hwy #64 and witnessed

Bearing Trees, Reference Objects

Species	Birch	Pople	Elm	_____
Diameter	10"	10"	6"	_____
Bearing	SW	NW	SE	_____
Distance	77.0'	78.8'	61.5'	_____

Bearing Trees, Reference Objects

Species	Pipe at	Ash	Re-rod	Power Pole
Diameter	R/W Sign	9"	1/2"	_____
Bearing	S 85° E	S 68° E	S 38° W	N 34° W
Distance	74.48'	84.34'	38.40'	92.77'

Subsequent Corner Restoration

Year surveyed 3/2017 By J. Kramer, LS 23668
Location filed: Certificate of Location
Monument: Set 1/2" iron pipe, RLS 23668
at computed location on centerline Hwy. #64 and witnessed.
Power Pole, N 45° W, 92.43'(2000) nail/disc, up 1'
Fence Post, S 88° W, 85.53' S. base


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R 17

CASS COUNTY LAND CORNER RECORD

T. 136 R. 32 M. 5TH Coordinates: X _____ Y _____
NE R 7 Corner common to sections 22, 23, 26, 27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1866
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>TAM.</u>	<u>TAM.</u>	<u>SPRUCE</u>	<u>SPRUCE</u>
Diameter	<u>18"</u>	<u>16"</u>	<u>5"</u>	<u>4"</u>
Bearing	<u>N26E</u>	<u>S11W</u>	<u>S46E</u>	<u>N52W</u>
Distance	<u>10 LKS</u>	<u>23 LKS</u>	<u>14 LKS</u>	<u>36 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 7/2000 By CCSO
Location filed file #2000,050
Monument Found 3/4" Pin, down 0.7', on E Hwy. #64.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Ash</u>	<u>Pi Pole</u>	<u>1/2" Red</u>	<u>R/W Man</u>
Diameter	<u>9"</u>			<u>in Conc.</u>
Bearing	<u>S68°E</u>	<u>N34°W</u>	<u>S38°W</u>	<u>S85°E</u>
Distance	<u>84.37*</u>	<u>92.77*</u>	<u>38.40'</u>	<u>74.48'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

March 1912 - Trip rd order shows no survey

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____