

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R 5

CASS COUNTY LAND CORNER RECORD

T. 136 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1866

Original monument Post

Species	Bearing	Trees	Distance
<u>SPRUCE</u>	<u>TAM</u>	<u>SPRUCE</u>	<u>TAM</u>
<u>5"</u>	<u>8"</u>	<u>8"</u>	<u>6"</u>
<u>S10E</u>	<u>N 55 1/2 W</u>	<u>S 77 W</u>	<u>N 41 1/2 E</u>
<u>3 LKS</u>	<u>17 LKS</u>	<u>27 LKS</u>	<u>15 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1918 By E. B. Hest

Location filed County Book "C" P. 108

Monument FIND GOUT BITS! 6" TAM N 41-30E 15 LKS, STUMP 8" TAM N 55-30 W 17 LKS, DOWN 5" SPRUCE SIDE 3 LKS, DOWN 8" SPRUCE S 77 W 27 LKS SET 2x48" T.M., - also on microf. film-roll 105 BK 65 P. 72

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>BALSAM</u>	<u>BALSAM</u>	
<u>4"</u>	<u>8"</u>	
<u>N 39-30W</u>	<u>S 38-15W</u>	
<u>40.7'</u>	<u>71.3'</u>	

Evidence of Subsequent Corner Restoration

Year of search 10/1904 By W. Hallett

Surveyors Report, Twp Road order Notes SW Corner Sec. 20.

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Aug. 1940; Twp rd order shows no survey

Remuneration certificate prepared _____ By _____

Filed at _____ Date _____