

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R 9

CASS COUNTY LAND CORNER RECORD

T. 136 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 29 Corner common to sections 20, 21, 28, 29



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1866
 Original monument Post

Bearing Trees
 Species TAM TAM
 Diameter 5" 12"
 Bearing S76 1/2 E N24W
 Distance 127 LKS 102 LKS.

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1918 By E. B. Horst
 Location filed County Book "C" P 108
 Monument Find Post & Cont. B.T. Stumps: TAM 12"
N 24W 102 LKS, TAM 5" S76-30E 127 LKS - SET
2x4" I.M.
also on micro film - roll 105 BK 65 P. 70-71

Bearing Trees, Reference Objects
 Species POPULAR TAM. Post
 Diameter 5"
 Bearing N40W SE
 Distance 139.5' 46.7'

Evidence of Subsequent Corner Restoration
 Year of search 1925 By GRENE
County Book "D" P. 171 Find old stake - but no iron
set iron P.P.E.

Bearing Trees, Reference Objects

R-9

Subsequent Corner Restoration
 Year surveyed 10/1904 By W. Hallett
 Location filed Twp. Road Order
 Monument Surveyor's Report shows
Road intersection.

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____