

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____

= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed: _____
Monument: _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

T. 137 R. 29 M. 5th Coordinates: X _____ Y _____
NE 31 Corner common to sections 29, 30, 31, 32



EXISTING SURVEYS

Original Government Survey			
Year surveyed <u>1865</u>			
Original monument <u>POST</u>			
Species	Bearing	Trees	
<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>
Diameter <u>10"</u>	<u>12"</u>	<u>14"</u>	<u>14"</u>
Bearing <u>N48E</u>	<u>N22W</u>	<u>S45W</u>	<u>S53E</u>
Distance <u>33LKS</u>	<u>50LKS</u>	<u>36LKS</u>	<u>10LKS</u>

Original Evidence Found	
Year of search _____	By _____
Monument found _____	
Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration			
Year surveyed <u>1910</u> By <u>JOHN CURO</u>			
Location filed <u>CONVLT SURVEY RECORD BOOK "A" P218-328</u>			
Monument <u>SET 8X8X36" CONCRETE POST BY DOUBLE PROPORTION</u>			
<u>1939, JOHN CURO, BOOK "D" P215 SET 2 1/4" X 18" I.P. FROM HIS OLD NOTES - CONCRETE GUN</u>			
Bearing Trees, Reference Objects			
Species <u>OAK</u>	<u>N. PINE</u>	<u>R. OAK</u>	<u>R. OAK</u>
Diameter <u>15"</u>	<u>18"</u>	<u>11"</u>	<u>5"</u>
Bearing <u>N38-40E</u>	<u>N5-20W</u>	<u>S33-20W</u>	<u>S10-50E</u>
Distance <u>95.70'</u>	<u>93.30'</u>	<u>35.50'</u>	<u>131.72'</u>
<u>1939 TIES</u>			

Evidence of Subsequent Corner Restoration	
Year of search <u>1914</u>	By <u>John Curo</u>
<u>microfilm - roll 115 BK 93 P. 108</u>	
<u>Find 8X8X36" cement post</u>	
Bearing Trees, Reference Objects	
_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration	
Year surveyed <u>1917</u>	By _____
Location filed _____	
Monument <u>Co DITCH SURVEY BK (9) BOX 3 OF Co DITCH SURVEY BOOKS, PG 2</u>	
<u>-Corner GPS 9/18/02 CC50 PK on E & CR #115 & 20th Ave</u>	

Evidence of Subsequent Corner Restoration Found	
Year of search _____	By _____
<u>CERTIFICATE - A.R. TAUBMAN - ASST HWY ENGINEER - 1927</u>	
<u>Set concrete monument 4"x4" top, 6"x6" base, 18" long. TIES: 4" concrete monument S37°55' W 46.67'; 4" concrete monument N52°05' W 46.67'.</u>	
<u>1998 - CC50</u>	
<u>fd. in place concrete monument. Removed during const. and set 60d penny spk.</u>	
<u>30" R. Oak</u>	<u>94.94' N 40° E</u>
<u>8" R. Oak</u>	<u>98.71' N 2° E</u>
<u>6" Aspen</u>	<u>91.52' N 12° W</u>
<u>8" Twin Maple</u>	<u>134.06' S 51° E</u>
<u>9/2000 - Re-set CNR from ties w/mag nail. Located at E C.R. 115 and E. & Twp Rd. to the South.</u>	