


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. X 13

CASS COUNTY LAND CORNER RECORD

T. 137 R. 31 M. 5TH Coordinates: X _____ Y _____
E 1/4 33 Corner common to sections 33, 34



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species W. BIRCH ASPEN
 Diameter 9" 12"
 Bearing S21W N54E
 Distance 16 LKS. 35 LKS.

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1920 By LINCOLN MARKET
 Location filed COUNTY RESURVEY E-46
 Monument IRON MONUMENT

Evidence of Subsequent Corner Restoration
 Year of search 6/2003 By CCSO
Found 2" ODIP, down 1.8', 4'±
E. of & old road grade, 60'±
S. of fence line to East.

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects
J. Pine Aspen R. Oak
13" 9" 13"
N18°W N88°E S58°W
90.68'* 24.07' 57.79'*
 *distance to double head nail

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
June 1905 R.H. Hallett
Two rd order shows survey

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____