

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. J 23

CASS COUNTY LAND CORNER RECORD

T. 138 R. 30 M. 5TH Coordinates: X _____ Y _____
N/4 13 Corner common to sections 12, 13



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Bl. Pine</u>	<u>Bl. Pine</u>	_____
Diameter	<u>6"</u>	<u>7"</u>	_____
Bearing	<u>S10W</u>	<u>N2W</u>	_____
Distance	<u>20 LKS.</u>	<u>40 LKS.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1979 By Co Hwy Dept.
Location filed Co Rd # 42
Monument 1 1/4" 1 1/2" 7.5' N of 4
1982 - set 1/2" rod.

Evidence of Subsequent Corner Restoration

Year of search 1998 By Landowner 17008
certificate of survey indicates monument found.

Bearing Trees, Reference Objects

Species	<u>W. oak clump</u>	<u>N. Pine</u>	<u>F.P.</u>
Diameter	<u>6"</u>	<u>14"</u>	_____
Bearing	<u>SE</u>	<u>SW</u>	<u>South</u>
Distance	<u>41.8'</u>	<u>43.4'</u>	<u>35.1'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

J-23

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument 6/2002 B. Grinn
Cert. of svy. shows mon. Found.

Evidence of Subsequent Corner Restoration Found

Year of search May 1905 By NW Hicks
Trwp rd order shows survey

July 2004 Jim Kramer
Sec. Subdivision shows computer corner

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____