


T. 13B R. 31 M. 5TH Coordinates: X _____ Y _____
E 1/4 3 Corner common to sections 2, 3



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument POST

Species	Bearing	Trees
<u>W. PINE</u>	<u>R. OAK</u>	
Diameter <u>12"</u>	<u>10"</u>	
Bearing <u>N 23 1/2 E</u>	<u>S 18 W</u>	
Distance <u>28 LKS.</u>	<u>24 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CRO

Location filed COUNTY RESURVEY 'E-47'

Monument 2 1/4 x 4 1/8" IRON MONUMENT

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1940 By CCC

Plats indicate nothing found at this corner

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1999 By CCSO

Location filed CCSO

Monument Ed cast iron flush, 2.0' E of E driveway, 180'± N. of E Hwy #87

10" W. Oak, N 10° W, 102.82 *

10" R. Oak, N 35° E, 34.51 *

8" Maple, S 86° E, 51.50 *

5" W. Oak, S 50° W, 42.04 *

* distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - AL WELLE - MINN DOT - 1981

Found 1" iron shaft. Set cast iron monument

Ties: 8" Elm N 11 W 71.26'; 8" Red Oak N 28 E 34.93'; 10" Elm S 22 E 37.70'.

Doc. # 262939.