

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R 13

CASS COUNTY LAND CORNER RECORD

T. 138 R. 31 M. 5th Coordinates: X _____ Y _____
NE 28 Corner common to sections 21, 22, 27, 28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>
Diameter	<u>4"</u>	<u>6"</u>	<u>12"</u>	<u>6"</u>
Bearing	<u>N47W</u>	<u>N2RE</u>	<u>S37W</u>	<u>S52E</u>
Distance	<u>6 LKS</u>	<u>13 LKS</u>	<u>35 LKS</u>	<u>22 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By ROY BRYANT
Location filed COUNTY SURVEY RECORD BOOK "B" P 286-288
Monument FND OLD GWT B.T.S DOWN: TAM 4" N47W
6 LKS, 6" TAM N2RE 13 LKS, 12" TAM S37W 35 LKS,
6" TAM S52E 22 LKS ALSO FND POST
1916, JOHN GREENE - BOOK "B" P 536-537 SET 2x48" TAM.

Evidence of Subsequent Corner Restoration

Year of search 1915 By J. A. JOHNSTON
COUNTY BOOK "B" P 587-588 FND OLD GWT POST
AND B.T.S: 4" TAM N47W 6 LKS, STUMP 12" TAM S37W
35 LKS, DOWN 6" TAM S52E 22 LKS SET 4" J. PLANE
1920, MORRIS, BOOK "C" P 391, FND TAM.
1915 - also on microfilm - roll 115 BK 88 P 33

Bearing Trees, Reference Objects

Species	<u>SPRUCE</u>	<u>TAM STAKE</u>	<u>TAM STAKE</u>	<u>DEAD TAM</u>
Diameter	<u>3"</u>	<u>4x48"</u>	<u>4x48"</u>	<u>6"</u>
Bearing	<u>N45E</u>	<u>N45W</u>	<u>S45W</u>	<u>S45E</u>
Distance	<u>46.7'</u>	<u>46.7'</u>	<u>46.7'</u>	<u>42.7'</u>

1916 B.T.S.

Bearing Trees, Reference Objects

1916 also on microfilm - roll 105 BK 53 P. 65
1915 - also on microfilm - roll 105 BK 58 P. 12

Subsequent Corner Restoration

Year surveyed 1915 By ROY BRYANT BK 108
Location filed Co Hwy Dept - in "Field Books" - notes
Monument on location of corners Co Ditch # 16
at 5387.3' from W. - corner is 5 57'
Found B.T.S. down - but found orig post.
140.7' N. of top of hill to S.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1983 - Marcum, Freeman, Bunn Found pipe
in swamp.

May 1915; Twp rd order shows no survey

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____