

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____
NE R 9 Corner common to sections 20, 21, 28, 29



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
 Original monument Post

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Bearing Trees

Species	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>
Diameter	<u>8"</u>	<u>9"</u>	<u>10"</u>	<u>5"</u>
Bearing	<u>N20E</u>	<u>S65E</u>	<u>S72W</u>	<u>N42W</u>
Distance	<u>14 LKS.</u>	<u>16 LKS</u>	<u>20 LKS</u>	<u>27 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1909 By JOHN CUVO
 Location filed COUNTY SURVEY RECORD BOOK 'A' P. 345
 Monument FIND OLD COT. B.T.S DOWN: 8" TAM N20E 9.2'
9" TAM S65E 10.6', 10" TAM S72W 13.2', 5" TAM. N42W
17.0', SET 4x4x8" POST

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK # 2 P. 30
at 5287' from west yellow tag on telephone
pole is 34' South
BK # 3 P. 4 38 ct 55' North from scribed by Ken
to C of Road, tag on tele. Pole 11' E of line
N. Line 29 = 180' ct.

Bearing Trees, Reference Objects

Species	<u>BALSAM</u>	<u>BALSAM</u>	_____	_____
Diameter	<u>6"</u>	<u>3"</u>	_____	_____
Bearing	<u>N54-58E</u>	<u>S41-27E</u>	_____	_____
Distance	<u>44.25'</u>	<u>33.36'</u>	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1971 By Co. Harry Dept
 Location filed Co. RP # 58
 Monument Corner

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1908 - John Cuvo - micro film - roll 115 BK 95 P. 4
Find all bearing trees down

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____