


Index No. V 21

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 35 Corner common to sections 25, 26, 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument lost

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	TAM.	TAM.	TAM.	TAM.
Diameter	<u>6"</u>	<u>6"</u>	<u>4"</u>	<u>4"</u>
Bearing	<u>N36E</u>	<u>N30W</u>	<u>S35E</u>	<u>S65W</u>
Distance	<u>23 LKS</u>	<u>39 LKS</u>	<u>43 LKS</u>	<u>45 LKS</u>

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Washburn Lake - BK#1 P59  
Monument Set App. for 52 00' from East - End  
3orig BITS - N10W 162'

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC  
Washburn Lake - BK#8  
Find all 4 BITS - do not measure to same point.  
Set 1 1/2" x 54" pipe 2 1/2' in ground w/ 2 1/4" steel cap  
random stake 29' W & 26' N

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Tam stub	Tam	dead tam	Tam
<u>3' high</u>	<u>8"</u>	<u>10"</u>	<u>9"</u>
<u>S52 1/2 W</u>	<u>N42 1/2 W</u>	<u>N26E</u>	<u>S36 1/2 E</u>
<u>28.2'</u>	<u>28.3'</u>	<u>11.55'</u>	<u>29.5'</u>

Subsequent Corner Restoration

Year surveyed Apr 1998 By C.C. Land Dept - AB, JJ  
Location filed Feb.  
Monument Mon. found good cond.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Mar 2003 - Found 1 1/2" ODIP, w/ scrape  
on cap, leans South, locate 2' down  
side of pipe. GPS Location

<u>7" Blk Spruce</u>	<u>N20° W</u>	<u>24.33'</u>
<u>10" Tamarack</u>	<u>N66° E</u>	<u>15.5'</u>
<u>7" B. Spruce</u>	<u>S60° E</u>	<u>7.44'</u>

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_