


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 21 Corner common to sections 15, 16, 21, 22



O = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1863
 Original monument Post

Species	Bearing	Trees	Distance
<u>W. Birch</u>	<u>W. Birch</u>	<u>W. Pine</u>	<u>W. Pine</u>
<u>6"</u>	<u>6"</u>	<u>20"</u>	<u>20"</u>
<u>N41E</u>	<u>S44E</u>	<u>S60W</u>	<u>N65W</u>
<u>18 LKS.</u>	<u>23 LKS.</u>	<u>35 LKS.</u>	<u>21 LKS.</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1937 By CCC
 Location filed Washburn Lake - BK#3 P. 37
 Monument Corner evidently in center of road - find
bits in brush pile set iron wood stake
1 1/2 CHS S. of road
1/4 cor is 47.7 CHS. west

Evidence of Subsequent Corner Restoration
 Year of search 1938 By CCC
Washburn Lake - BK#9, subdivision of sec 16
corner in center of road
1938 - BK#20 P. 41 corner 18' S. of Camp road

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search SEPT. 2000 By CCSO
Find in place; RR spike, down 0.4' E C.R. 48
and 85' W of E Crooked Lk. Trail. Found
old blazes and nails in 3 B.T.'s.
 REF. TIES:
22" W. Pine N 18° W 84.79'
11" W. Oak N 18° E 79.72' (old blaze)
11" R. Oak N 46° E 74.28' (old blaze)
8" Ash S 2° E 57.81' (old blaze)
 CORNER GPS CCSO 8/14/02
CCSO 8/14/02 Ed R.R. spike, down
0.4, on E co. Ad. #48