


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. C 13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5th Coordinates: X _____ Y _____
E1/4 4 Corner common to sections 3, 4



○ = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1864
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species W. Pine J. Pine
Diameter 6" 6"
Bearing S50W S60E
Distance 25 Lks. 10 Lks

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1911 By John Curd
Location filed COUNTY BOOK A P. 364-368
Monument FMS STAKE SET BY CURD FROM OLD CO. VY B.T.S. SET 8X8X36" CONCRETE POST
1922 - COUNTY RESURVEY 'E-9' IRON MONUMENT

Evidence of Subsequent Corner Restoration
Year of search 1982 By Co. SURVEYOR
FND CONCRETE POST IN Q. N-S ROAD DOWN 0.1'
1911 - micro film - Harry Todd - roll 115 BKT 3 P. 35
SET 8X8X36" CONCRETE POST FROM B.T.'S

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects
ASPEN P.P. W. PINE
5" 8" 1982
S64W N37E N30W 7.13
36.64' 47.33' 67.24'
NAIL S. SIDE NAIL NW. SIDE NAIL E. SIDE

C-13

Subsequent Corner Restoration
Year surveyed 1999 By CCSO
Location filed CCSO
Monument Concrete monument flush, 3.5' E of Q. Co. Rd. 56, witnessed as follows:

- 15" W. Pine, N38°W, 67.02' *
- 8" Spruce, S60°E, 52.92 (old blaze) *
- 12" Balsam, S58°W, 43.07 (old blaze) *
- Survey Sign, West, 32.4'
- * denotes double head spike
- denotes 16d spike found

7-28-99 - CCSO replaced concrete block w/ 1/2" ODIP w/ cap - RLS 16459 down 0.4' in gravel rd. Concrete man. was removed intact and placed by survey sign.

Dec. 1918, Twp rd order shows no survey

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

Re monumentation certificate prepared _____
Filed at _____

By _____
Date _____