


T. 139 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 11 Corner common to sections 36



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1865  
 Original monument POST

Bearing Trees  
 Species TAM. TAM  
 Diameter 6" 12"  
 Bearing N55E S84E  
 Distance 245 LKS 253 LKS.

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1985 By Walt Curo  
 Location filed Corner Certificate  
 Monument Find remains of a post set in 1924 for a W.C.M.C. also find rotted Tam bit. SE that checks for M.C. (in lake) set 2x2x36" sq. County iron w/ aluminum cap W.C.M.C. 46.50' East of tree M.C.

Bearing Trees, Reference Objects  
 Species Spruce Ash old katted Ash  
 Diameter 8" 6" Tam stump 5"  
 Bearing N33E S88E S80E S62E  
 Distance 207.68' 134.26' 120.5 67.16  
aluminum tags on trees

Evidence of Subsequent Corner Restoration  
 Year of search 1974 By F.A. Donney  
microfilm - roll 115 BK 94 P. 74  
find old set 4x4x48" Ash post also set WCML 589-45E 46.50'

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Walt Curo 1985  
Doc # 280482