


Index No. F-6 17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 32 Corner common to sections 10, 11



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	Bearing	Distance
<u>TAM.</u>	<u>TAM.</u>	
<u>8"</u>	<u>6"</u>	
<u>545E</u>	<u>544W</u>	
<u>33 LKS</u>	<u>26 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1987 By Lundecker  
Certificate - Doc # 300478  
Set 2" Sq iron w/ aluminum cap WC MC  
orig. falls in lake - use Greene's 1925 information

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>N. Pine</u>	<u>5"</u>	<u>N 32 E</u>	<u>16.74'</u>
<u>11"</u>	<u>Capped iron</u>	<u>EAST</u>	<u>20.3</u>
	<u>cabn corner</u>	<u>26.14'</u>	
	<u>(NW)</u>		
	<u>(SW)</u>		
	<u>523E</u>		
<u>1" I.P.</u>	<u>522°E</u>	<u>28.19'</u>	<u>1/4 cor. SOUTH 620.00'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Dave Lundecker - 1987

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_