


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. J 25

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 13 Corner common to sections 12, 13



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>ASPEN</u>	<u>Y. BIRCH</u>	
<u>9"</u>	<u>10"</u>	
<u>S45W</u>	<u>N60W</u>	
<u>18 LKS</u>	<u>24 LKS.</u>	

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1931 By P. WARNER
Location filed IN TWP. FILE
Monument PIPE

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washington Lake - BK # 2 P. 58
Start west from cor.

Information from ITASCA Co.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>oak</u>	<u>4"</u>	<u>N70E</u>	<u>42.8'</u>
<u>FENCE POST</u>	<u>7"</u>	<u>S83W</u>	<u>30.9'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search Nov. 1905 By _____
Trwp rd order shows no survey

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____