


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 140 R. 26 M. 5th Coordinates: X _____ Y _____
N14 10 Corner common to sections 3, 10



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST
Notes show corner in Spruce swamp

Bearing Trees

Species	<u>Spruce</u>	<u>Spruce</u>	_____
Diameter	<u>4"</u>	<u>3"</u>	_____
Bearing	<u>N 8 E</u>	<u>S 40 E</u>	_____
Distance	<u>10 lbs</u>	<u>14 lbs</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1989 By David Landscker
Set 2" iron pipe up 12"

Bearing Trees, Reference Objects

<u>Red Oak</u>	<u>Tamarack</u>	<u>& State</u>
<u>8"</u>	<u>7"</u>	<u>Hwy # 6</u>
<u>N 36 W</u>	<u>S 88 W</u>	<u>East</u>
<u>36.26'</u>	<u>37.99'</u>	<u>82'±</u>

E-15

Subsequent Corner Restoration

Year surveyed 1965 By R.F. Schneider
Location filed _____
Monument Found 2" Iron Pipe

Ties: 18" N. Pine N1E 109.7 } Book "D"
6" Spruce S77W 29.55 } P. 455

E - 15

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Cert. Filed by David Landscker
Doc. # 317221

Feb 1992 T Freeman # 21367
Cert of Survey shows monument found