


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____

Year of search _____ by _____

Original monument _____

Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____


Monument: _____

Monument: _____

Index No. R 9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 29 Corner common to sections 20, 21, 28, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	B. PINE	B. PINE	B. PINE	B. PINE
Diameter	<u>12"</u>	<u>12"</u>	<u>8"</u>	<u>4"</u>
Bearing	<u>SR6E</u>	<u>NR4E</u>	<u>N4W</u>	<u>S81W</u>
Distance	<u>26 LKS</u>	<u>33 LKS</u>	<u>21 LKS</u>	<u>46 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By N. D. Goeman
Location filed COUNTY BOOK 8 P 465-468
Monument Two STAKE & NEW B.T.S (Below)
also on microf. film - vol 115 BK 88 P. 15
1975 - Co Hwy Dept - Co Rd # 40 - 2" capped
pipe

Evidence of Subsequent Corner Restoration

Year of search 1980 By G. H. Stevenson
2" capped I.M.

Bearing Trees, Reference Objects

Species	TAM	TAM	DEAD SPRUCE
Diameter	<u>20"</u>	<u>16"</u>	<u>10"</u>
Bearing	<u>S3-21E</u>	<u>N13-20E</u>	<u>N46-27W</u>
Distance	<u>16.60'</u>	<u>21.90'</u>	<u>12.85'</u>

1915 B.T.S

Bearing Trees, Reference Objects

Spruce	Spruce	Balsam
<u>6"</u>	<u>5"</u>	<u>10"</u>
<u>N37W</u>	<u>N75W</u>	<u>N65W</u>
<u>42.38'</u>	<u>67.99'</u>	<u>68.50'</u>

Subsequent Corner Restoration

Year surveyed 1983 By Freeman - Olson
Location filed Survey Tech - Wildlife Manager
Monument End 2" capped pipe & 1980 ties

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Oct. 2004 T. Freeman #21367
Cert. of Survey shows monument found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____