


T. 141 R. 26 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 1 Corner common to sections 1 and 6-141-25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Aspen</u>	<u>Fir</u>
Diameter	<u>8"</u>	<u>4"</u>
Bearing	<u>N 81° E</u>	<u>S 64° W</u>
Distance	<u>14 links</u>	<u>13 links</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed Circ 1927 By MN/DOT  
Location filed: Hwy Plan 3-8, TH 6, on web site as #1947787  
Monument: Indicates an Iron Pin 5" below surface at intersection of old roads and witnesses as follows.

Evidence of Subsequent Corner Restoration

Year of search 11/1935 By MN/DOT  
Location filed: Hwy Plan 6-61, TH 200, on web site as #1947404  
Monument: Indicates Iron Pin 5" below surface at intersection of old roads, 708.2', N. of centerline Trunk Highway #34 now Highway #200.

Bearing Trees, Reference Objects

Species	<u>Poplar</u>	<u>Pine</u>	<u>Elm</u>
Diameter	<u>8"</u>	<u>24"</u>	<u>8"</u>
Bearing	<u>WSW</u>	<u>ESE</u>	<u>SE</u>
Distance	<u>95.0'</u>	<u>88.2'</u>	<u>49.0'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 7/1977 By M.E. Stefan, LS 12261  
Location filed: USFS T141N R25W, Field Book 2, page 7  
Monument: Found a steel pin T141N in center of road, 6" below surface on R26W R25W fence line to N. and S. Steel Pin has 1/4 been in place many years. It has been S 1 | S 6 used as the 1/4 corner for Town of Remer, 1978 Fences N. - S. & Road E. - W. I accept RLS No. 12261 its position as the 1/4 corner between S. 1&6. Set a 6" concrete post in place of iron, down 18", with brass tablet. and witnessed as follows:  
1.5" Pipe, North, 25.7'  
Fence Post, South, 25.7'  
Fence Post, N 15° W, 28.1'  
Fence Post, S 5° W, 26.0'  
7" W. Oak, N 34° W, 43.10'  
18" W. Oak, S 46° W, 108.45'  
17" W. Oak, S 74° E, 96.60'  
Steel Post, North, 25.5'  
  
5/1985, G.H. Stevenson, LS 12684  
Worksheet for Section 1  
Indicates a USFS Monument at the subject corner.

Evidence of Subsequent Corner Restoration Found

Year of search 4/1989 By W.E. Curo, LS 11395  
Location filed: Survey for Zylka, Curo Book 321 page 51  
Monument: Indicates monument  
  
10/1994, W.E. Curo, LS 11395  
Certificate of Survey for Hansen and Curo Book 335, page 75  
Indicates Iron monument found in place at the subject corner.  
  
8/1998, CCHD/SO  
#1998.007  
Found Concrete Cylinder with brass cap, down 0.8', 1', +/-, N. of centerline 70th St. and witnessed as follows.  
10" W. Oak, N 41° W, 42.71'  
20" W. Oak, S 46° W, 108'  
20" W. Oak, S 76° E, 96.60'  
14" W. Oak, S 72° W, 70.27' duplex nail, up 1.2', N. side  
  
9/1999, M.E. Stefan, LS 12261  
Certificate of Survey for Andrews in Section 1, #874  
Indicates 6" Concrete Cylinder/Bass Cap monument found.  
4/2001, J.J. Bunkowske, LS 24606  
Certificate of Survey for Duro in Section 1, #1151  
Indicates a monument found at the subject corner.

T. 141 R. 26 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

E 1/4 1 Corner common to sections 1 and 6-141-25

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed 4/2018 By CCHD/SO

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed: #2017.030

Location filed: \_\_\_\_\_


Monument: Found USFS Concrete Monument with brass cap down 0.8', 1', +/-, N. of centerline of 70th St. and witnessed. 16" W. Oak, S 72° W, 70.27'(1998) duplex nail, up 1.2', N. side 18" W. Oak, N 61° W, 32.02' duplex nail, up 1.0', N. side 6" B. Oak, N 62 E, 74.67' duplex nail, up 1.0', N. side 1.5" Iron Pipe, North, 25.42'

Monument: \_\_\_\_\_

Index No. C 25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 76 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 Corner common to sections 1 AND 6-141-25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>ASPEN</u>	<u>FIR</u>
Diameter <u>8"</u>	<u>4"</u>
Bearing <u>N81E</u>	<u>S64W</u>
Distance <u>14 LKS</u>	<u>13 LKS</u>

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1927 By Miss Hwy Dept.  
Location filed R/W map in Recorder's office - Remy  
Monument to Cohasset  
Corner at P.I. (old) roads.

Evidence of Subsequent Corner Restoration

Year of search 1998 By CCSO  
Fd. FS Monument down 0.8', 1.0' N. of E  
Gravel Rd. (70<sup>th</sup> St.)

Bearing Trees, Reference Objects

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Bearing Trees, Reference Objects

W. Oak	W. Pine	W. Oak	W. Oak
<u>10"</u>	<u>20"</u>	<u>20" 14"</u>	<u>20"</u>
<u>N 41° W</u>	<u>S 77° E</u>	<u>S 72° W</u>	
<u>42.71'</u>	<u>96.60'</u>	<u>70.27'</u>	<u>109'</u>

NO SPK. (CORNER)

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_