


T. 141 R. 27 M. 5th Coordinates: X _____ Y _____
M.C. #9 Corner common to sections 3, 10

N 87°49' W 1.05 chains



EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed <u>1874</u>	Year of search _____ by _____
Original monument <u>Post</u>	Monument found _____

Bearing Trees

Species	<u>Birch</u>
Diameter	<u>5"</u>
Bearing	<u>S 10° E</u>
Distance	<u>14 links</u>

Original Bearing Trees Found

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 3/1972 By W.J. Spain, LS 2003
 Location filed: LA CASA J & R, Doc. #204321
 Monument: Indicates monument in place

Evidence of Subsequent Corner Restoration

Year of search 10/1987 By R.L. Kovanen, LS 16459
 Location filed: Certificate of Location
 Monument: Found I Beam at position indicated on Plat.

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 1/1988 By R.L. Kovanen, LS 16459
 Location filed: Certificate of Location T141N R27W
 Monument: Set 2" USFS iron pipe w/brass cap WCMC
as witness corner, 6.70' W. of lost MC position. S 3 / WC
7" Red Oak, N 56° W, 26.41' 20d spike S 10 / MC
8" Red Oak, S 64° W, 24.75' 20d spike 1988
8" Red Oak, S 11° W, 35.10' 20d spike RLS 16459

Evidence of Subsequent Corner Restoration Found


Year of search _____ By _____
 Location filed: _____
 Monument: _____

7/2018, CCHD/SO
 #2017.018
 Found 2" USFS iron pipe with brass cap, up 2.1', 14'+/-, W. of Mabel Lake and witnessed.
 8" Red Oak, S 11° W, 35.10'(1988) 20d spike, up 1.2', E. side
 8" Maple, N 74° W, 19.36' duplex nail, up 1.0', S. side

Index No. E 15-16

CASS COUNTY LAND CORNER RECORD

T. 141 R. R7 M. 5th Coordinates: X _____ Y _____
MC # 9 Corner common to sections 3, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species BIRCH
Diameter 5"
Bearing S10E
Distance 14 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1988 By Robert Kovanen
Corner Cert. Sicate - Doc # 302624
Set 2x48" l.p. w/ brass cap 6.70' W. of
lost position for MC.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Red oak Red oak Red oak
7" 8" 8"
N56W S64W S11W
26.41' 24.75' 35.10'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - LA CASA J & R
W. J. SPAIN 1972
Certificate - Robert Kovanen - 1988

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____