


T. 141 R. 27 M. 5th Coordinates: X _____ Y _____
N 1/4 15 Corner common to sections 10, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Poplar</u>	<u>Poplar</u>
Diameter	<u>4"</u>	<u>4"</u>
Bearing	<u>South</u>	<u>N 25° W</u>
Distance	<u>47 links</u>	<u>36 links</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 11/1968 By C. Krause, USFS
Location filed: USFS Field Book 2, page 68
Monument:
Chained W. from Sec. Cor., fell E. of fence line N. Checked along road with dip needle, no monument or evidence.

Evidence of Subsequent Corner Restoration

Year of search 10/1987 By R.L. Kovanen, LS 16459
Location filed: Certificate of Location
Monument: Found 8" spike down 1', 3' N. of centerline, on fence line N. FSLP on post, N. 19.22', reads S. 0.28(18.48') to 1/4 cor. R. Main, USFS estimates this tag as circa 1930, CCC.

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1/1988 By R.L. Kovanen, LS 16459
Location filed: Certificate of Location T141N R27W
Monument: Set 2" iron pipe with brass cap 1/4 down 1', at found spike location and witnessed. S 10 8" Oak, N 46° W, 59.63' 20d spike S 15 14" Oak, N 11° W, 33.95' 20d spike 1988 10" Oak, S 28° W, 63.09' 20d spike RLS 16459 Cedar Post, North, 19.2' FSLP Steel Sign Post, South, 28.72'

Evidence of Subsequent Corner Restoration Found

Year of search 9/2018 By CCHD/SO
Location filed: #2017.018
Monument: Set 1" x 30" Aluminum County monument down 0.5', 2' +/- N. of centerline Co. Rd. #129. 11/1/2018, T.L. Freeman, LS 21367 Filed a Certificate of Location of Gov't Corner, as Document #A000645584, on the above information.


10/2005, CCHD/SO
#2001.016
Found 2" ODIP, cap gone, flush, 2'+/-, N. of centerline witnesses are all good.

7/2018, CCHD/SO
#2017.018
Found 2.0" ODIP, cap gone, top 1' bent, locate base and witnesses as follows.
11" Burr Oak, N 46° W, 59.63'(1988) 20d spike, up 0.9', S. side
15" Burr Oak, N 11° W, 33.95'(1988) 20d spike, up 0.9', E. side
11" Burr Oak, S 28° W, 63.09'(1988) 20d spike, up 1.0', E. side
Steel Sign Post, South, 28.7'(1988)

Index No. J15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
N1/4 15 Corner common to sections 10, 15



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1874
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing	Trees
<u>POPLAR</u>	<u>POPLAR</u>	
<u>4"</u>	<u>4"</u>	
<u>SOUTH</u>	<u>N 25 W</u>	
<u>47 LKS</u>	<u>36 LKS</u>	

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search 1988 By Robert Kovanen
Corner Certificate - Doc # 302601
Find spike - Set 2x24" brass cap monument
8" steel sign post South 28.72'

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Species	Bearing	Reference Objects
<u>OAK</u>	<u>OAK</u>	<u>OAK</u>
<u>10"</u>	<u>14"</u>	<u>8"</u>
<u>S 28 W</u>	<u>N 11 W</u>	<u>N 46 W</u>
<u>63.09'</u>	<u>33.95'</u>	<u>59.63'</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
Certificate - Robert Kovanen - 1988

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____