


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed: _____
Monument: _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. R9

CASS COUNTY LAND CORNER RECORD

T. 141 R. R7 M. 5TH Coordinates: X _____ Y _____
NE 29 Corner common to sections 20, 21, 28, 29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			Species
	TAM.	TAM.	CEGAR	
Diameter	<u>5"</u>	<u>8"</u>	<u>7"</u>	<u>6"</u>
Bearing	<u>S16E</u>	<u>N37E</u>	<u>N10W</u>	<u>S47W</u>
Distance	<u>9 LKS</u>	<u>26 LKS</u>	<u>12 LKS</u>	<u>17 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLD
Location filed SECRETARY OF STATE
Monument FIND OLD WOOD POST AND BITS: 12" TAM. N37E 26 LKS AND 5" CEDAR STUMP S16E 9 LKS

Evidence of Subsequent Corner Restoration

Year of search 1923 By J.H. FLYNN
COUNTY BOOK D' P. 116 FIND CORNER

Species	Bearing Trees, Reference Objects			Species
	CEGAR	CEGAR	CEGAR	
Diameter	<u>10"</u>	<u>10"</u>	<u>8"</u>	<u>8"</u>
Bearing	<u>N56-15E</u>	<u>S67-15E</u>	<u>S32-15W</u>	<u>N70-45W</u>
Distance	<u>21 LKS</u>	<u>57 LKS</u>	<u>34 LKS</u>	<u>24 LKS</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1968
Found 2" x 3" iron pipe with marked brass cap; 10" Cedar N56°15'E 13.9' now 16"; 8" Cedar S32°15'W 22.4' now 16"; 8" Cedar N70°45'W 15.8' now 12". Ties: 12" Cedar S65 E 60.14'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____