


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1874
 Original monument POST

Bearing Trees	
Species <u>TAM.</u>	<u>TAM.</u>
Diameter <u>8"</u>	<u>14"</u>
Bearing <u>NEOW</u>	<u>N35E</u>
Distance <u>26LKS.</u>	<u>21LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1919 By GLO
 Location filed SECRETARY OF STATE
 Monument FIND OLD GOVT B.T.: 14" TAM S55E 30LKS.
SET 2x36" I.P. w/ BRASS CAP

1919	
<u>T191N R27W</u>	<u>529 528</u>
	<u>532 533</u>

Evidence of Subsequent Corner Restoration
 Year of search 1923 By J.H. FLYNN
COUNTY BOOK "D" P. 116 FIND GOVT IRON MONUMENT.

Bearing Trees, Reference Objects

1919			
Species <u>SPRUCE</u>	<u>W. OAK</u>	<u>TAM.</u>	<u>TAM.</u>
Diameter <u>8"</u>	<u>16"</u>	<u>10"</u>	<u>16"</u>
Bearing <u>N57E</u>	<u>S5E</u>	<u>S81-15W</u>	<u>N41-45W</u>
Distance <u>60LKS</u>	<u>109LKS</u>	<u>93LKS</u>	<u>72LKS</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1968
Found stump for 8" Spruce N57E 39.6';
Found stump for 10" Tamarack S81°15'W
61.3'; Found stump for 16" Tamarack
N41°45'W 47.5'.
Set 6" x 2' cylindrical concrete
monument capped with 3" stamped
brass tablet. Ties: 7" Tamarack N20W
155.76'; 10" Tamarack N66E 173.82'; 10"
W. Oak S34E 61.19'; 10" W. Oak
S48W 116.98'.