

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. 29

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5th Coordinates: X _____ Y _____
SE 32 Corner common to sections 32, 33



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1865
 Original monument POST

Bearing Trees
 Species FIR CEDAR
 Diameter 6" 9"
 Bearing N29W N60E
 Distance 15 LKS. 44 LKS.

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1913 By HARRY S. TODD
 Location filed COUNTY SURVEY RECORD BOOK "A" P 568-570
 Monument SET 4x4x40" STAKE
1919 - GLO - FND 4" SQUARE WOOD POST NO BITS - DID NOT SET IRON
1923, FLYNN, BOOK "D" P 116 FND CORNER.

Bearing Trees, Reference Objects
 Species POPLAR POPLAR
 Diameter 12" 10"
 Bearing N46-30W N34-15E
 Distance 62.65' 70.70'
1913 TIES.

Evidence of Subsequent Corner Restoration
 Year of search 1974-1978 By MIL0 STEFAN
PLAT OF SURVEY "E-72" 6x6x24" CONCRETE POST
W/ 3" BRASS CAP. FROM EVIDENCE OF CASS CO. SURVEYORS, RECORD OF 1942 IN BOOK "D"
1942 - JOHN CUCO - BOOK "D" P 305. TIES: 12" CEDAR N132-23W 121.30', TWIN CEDAR 5" N51-02E 92.18', 16" POPLAR N59-50E 85.32'

Bearing Trees, Reference Objects
 CEDAR CEDAR CEDAR CEDAR STEEL SIGN POST
 19" 12" 15" 12" SOUTH
 N54W N32W N33E N57E 1.0'
 134.9' 158.2' 98.6' 133.4'
1974-78 TIES

Subsequent Corner Restoration
 Year surveyed 1938 By CCC
 Location filed Washburn Lake - BK # 5 P. 59.
 Monument 1/4" at road intersection E-W-N marked C-P-C

Mar 2003 CCSD
Found Brass Cap in conc. 20' ± S. of E Danens Drive, 4' ± W. of cor. rd. #129. All 1974 witnesses in good condition.

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____