


T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 6 Corner common to sections 6 AND 31-142-28



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>ELM</u>	<u>POPLAR</u>	
<u>16"</u>	<u>4"</u>	
<u>N20W</u>	<u>SSE</u>	
<u>10 LKS</u>	<u>15 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By John Curo, EA  
Location filed COUNTY BOOK B P 391-398  
Monument SET 2x4x8" IRON

Evidence of Subsequent Corner Restoration

Year of search 1918 By GLO  
FILED AT: SECRETARY OF STATE - FWD 2" GALV.  
I.P. AND GALT B.T.: DOWN 16" ELM N20W 10 LKS  
SET 1x36" I.P. W/ BRASS CAP. 14 53/56  
1918

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>POPLAR</u>	<u>14"</u>	<u>S26 1/2 W</u>	<u>69 LKS</u>
<u>ELM</u>	<u>14"</u>	<u>N52 3/4 W</u>	<u>30 LKS</u>
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1973  
Found GLO monument in good shape.  
Ties: 5" Ash S60W 9.50'; 5" Ash S82W  
19.10'; 9" Ash N30E 45.60'.