


T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 24 Corner common to sections 2, 3



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>BIRCH</u>	<u>W. PINE</u>
Diameter <u>7"</u>	<u>6"</u>
Bearing <u>S 49W</u>	<u>S 52E</u>
Distance <u>14 LKS</u>	<u>90 LKS</u>

Original Bearing Trees Found		
Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By GLO  
Location filed SECRETARY OF STATE  
Monument FIND OLD DELAYED STAKE SET 1836"  
1/4 W/BRASS CAP MC  
53 52  
T141N R28W  
1921

Evidence of Subsequent Corner Restoration

Year of search 1988 By Walt Curro  
Corner Certificate - Doc # 303288  
Find brass cap 10' S. of shore

Bearing Trees, Reference Objects

Species <u>ROAK</u>	<u>BIRCH</u>
Diameter <u>6"</u>	<u>12"</u>
Bearing <u>S 59 1/2 E</u>	<u>N 35 3/4 W</u>
Distance <u>16 LKS</u>	<u>27 LKS</u>

Bearing Trees, Reference Objects

<u>Burr oak</u>	<u>Birch</u>	<u>Red oak</u>
<u>4"</u>	<u>9"</u>	<u>6"</u>
<u>N 63 W</u>	<u>N 71 E</u>	<u>S 41 E</u>
<u>41.75'</u>	<u>5.10'</u>	<u>26.28'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Walt Curro - 1988  
1999 - Certificate Filed # 410195  
James Kramer RLS # 23668. Found  
1988 witnesses Birch now 12", add  
steel sign post 3.5' SW.