


T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
NE10 Corner common to sections 2,3,10,11



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
 Original monument POST

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Bearing Trees

Species ELM OAK
 Diameter 8" 9"
 Bearing S4W N7E
 Distance 60 LKS 80 LKS

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1915 By John Curo
 Location filed COUNTY SURVEY RECORD BOOK 8 P 169-177
 Monument FIND OLD COTT W. OAK STAKE SET 2 1/2 X 4 1/8'
FROM MONUMENT
1917, E.B. HIRST BOOK 8, P 601-603 FIND T.M.
1915 - Baldwin - microf. Im - vol 1165 BK 60 P 112-113
FIND CORNER - OAK W. OAK STAKE - SET 2 1/2 X 4 1/8" T.M.

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1918 By GLO
 FILED AT: SECRETARY OF STATE FIND 3" I.P.
SET 2X36" I.P. W/ BRASS CAP | TI4IN RR2W
ORIG. B.T.S: OAK STUMP 12" N70 1/2 E 80 LKS | S3 | S2
STUMP HOLE S0-45E 60 LKS | S10 | S11
1918

Bearing Trees, Reference Objects

| | | | |
|----------------|----------------|----------------|----------------|
| <u>POPLAR</u> | <u>W. OAK</u> | <u>POPLAR</u> | <u>N. PINE</u> |
| <u>8"</u> | <u>16"</u> | <u>8"</u> | <u>6"</u> |
| <u>N49-45E</u> | <u>S61-15E</u> | <u>S55-45W</u> | <u>N36W</u> |
| <u>339 LKS</u> | <u>334 LKS</u> | <u>219 LKS</u> | <u>315 LKS</u> |

E-17

Subsequent Corner Restoration

Year surveyed 1923 By Mrs. Hwy Dept
 Location filed R/W map in Recorder's office - 15 mi E
 Monument of Walker to 12 mi W. of Remer.
Brass Cap in road at P.L. Sta. 471+27.5

OCT 2002 T. Freeman 21367
Cert. of Surv. shows mon. found

Remonumentation certificate prepared _____
 Filed at _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Walt Curo - 1987
Doc # 301680
Find 1" iron bar in road
Set 2" sq x 18" telescope monument
30" Burr oak N 65 E 194.26'
13" Burr oak S 33 E 70.06'
8" Burr oak S 22 W 60.45'
6" Poplar N 62 W 102.40'

MNDOT
1999 - ~~550~~ Cert. of Loc. Doc. # 410185
Fd. - 2" Sq. telescope tube mon., cap missing,
down 0.3' E of Hwy. 200

6" Poplar - N 62° W 102.40'
30" Burr Oak N 65° E 194.26'
13" Burr Oak S 33° E 70.06'
8" Burr Oak S 22° W 60.45'

1999 - MNDOT Cert. of Survey indicates
monument mentioned above to
be impl.

By _____
 Date _____