


T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
N1/4 8 Corner common to sections 5, 8



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
 Original monument Post

Bearing Trees

Species N. Pine
 Diameter 16"
 Bearing N23W
 Distance 80 LKS

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1915 By John Curo
 Location filed COUNTY SURVEY RECORD BOOK "B" P. 169-177
 Monument SET 2 1/2 X 4 1/2" IRON MONUMENT PROPORTIONALLY

Also on microfilm - roll 105 BK 60 P. 1110

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1918 By GLO
 FILED AT: SECRETARY OF STATE FND 2" GALL.
 I.P. SET 1 X 3/8" I.P. W/ BRASS CAP - PROPORTIONALLY
 POSITION 1/4 55
58
1918

Bearing Trees, Reference Objects

POPLAR w. OAK
8" 8"
N73E S14W
297 LKS 546 LKS

E-7

Subsequent Corner Restoration

Year surveyed 8/2001 By CCSO
 Location filed CCSO
 Monument 1918 GLO Brass cap, up 1.5',
0.65' South of 2" IP w/ plumbers
cap, 110'± S. of 2 Hwy #200 at
North edge of swamp, USFS
Steel sign post West, 3.3'. Add
the following witnesses:

- 8" W. Oak N13°E, 30.08* (1971 tag)
- 8" W. Oak N32°W, 38.35*
- 6" W. Oak N68°W, 38.21*
- *distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1971
Found GLO monument in good condition.
Ties: 17" OAK S14W 360.4'; 5" OAK N28W
4.5'; 6" OAK N73W 32.7'; 6" OAK N13E
29.9'.