


T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
MC # 33 Corner common to sections 11, 14



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1874
 Original monument POST

Bearing Trees
 Species DEAD W. PINE
 Diameter 23"
 Bearing N 56 W
 Distance 117 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1918 By GLO
 Location filed SECRETARY OF STATE
 Monument 2 MONUMENTS SET - ONE AT PROPORTIONAL POSITION - SET 1X36" I.P. W/ BRASS CAP - THE OTHER AT PRESENT SHORELINE - SET 1X36" I.P. W/ BRASS CAP. BOTH MARKED THE SAME ON BRASS CAP.

Bearing Trees, Reference Objects

Species	<u>W. OAK</u>	<u>W. OAK</u>	<u>W. OAK</u>	<u>W. OAK</u>	<u>TI 1/4 IN R 28 W</u>
Diameter	<u>8"</u>	<u>12"</u>	<u>10"</u>	<u>8"</u>	<u>5 1/2" MC</u>
Bearing	<u>N 43 1/4 W</u>	<u>S 48 3/4 E</u>	<u>S 53 1/4 W</u>	<u>N 61 3/4 W</u>	<u>5 1/4" MC</u>
Distance	<u>49 LKS</u>	<u>86 LKS</u>	<u>149 LKS</u>	<u>630 LKS</u>	<u>1918</u>

PROPORTIONAL SHORELINE

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

PRESENT SHORELINE 2.70 CH EAST OF PROPORTIONAL POSITION

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1971
CERTIFICATE - MILO STEFFAN - 1979 Doc # 246377
Certificate David Landecker 1992
Doc # 334682
Found 1" iron pipe with brass cap
up 9". Ties: 18" Burr Oak N 43 W 276.54';
9" Burr Oak S 50 E 30.04'; 9" Burr Oak
S 39 W 32.74'; 8" Burr Oak N 70 W
59.05'.