


T. 141 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 22 Corner common to sections 22, 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_ NO TREES \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 9/1918 By E.G. Harrington, GLO  
Location filed: Minnesota Historical Society, notes 35 1/4  
Monument: Set 1"x 36" Iron pipe with brass cap at proportionate position and witnessed. S22 | S23 1918

Evidence of Subsequent Corner Restoration

Year of search 3/1980 By R.A. Mustonen, LS 11946  
Location filed: Certificate of Section breakdown, #7162  
Monument: GLO Monument found subdivision of the SW 1/4.

Bearing Trees, Reference Objects

Species Norway Pine Tamarack  
Diameter 10" 6"  
Bearing S 22 1/4° E S 33 1/2° W  
Distance 55 links 152 links

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 5/1986 By R.A. Mustonen, LS 11946  
Location filed: Certificate of Survey, #7164  
Monument: Found GLO Monument  
  
8/1986, R.A. Mustonen, LS 11946  
Certificate of Survey, #686  
Indicates found GLO monument.  
  
2/1987, CCHD  
County Project 97-1, Corner Location notes and Plan sheet 9  
Indicates Iron Pipe 5.3 meters (17.4') Rt. at station 1+040.  
Removed monument due to construction on Co. Rd. #126.  
  
1/1998, R.A. Mustonen, LS 11946  
Certificate of Survey for Magnus, #685  
Indicates position for the corner.  
  
6/2000, CCHD/SO  
#99025  
Reset GLO brass cap monument, down 0.2', 17.5', S. of CL.  
Position reestablished from R.A. Mustonen information  
20" Red Pine, S 20° E, 35.82'(1918) duplex nail, up 1.0', E. side  
14" Red Oak, N 2° E, 111.07' duplex nail, up 1.0', W. side  
18" Red Oak, S 62° E, 108.06' duplex nail, up 1.0', N. side  
13" Red Pine, N 20° W, 100.53' duplex nail, up 1.0', W. side


Evidence of Subsequent Corner Restoration Found

Year of search 10/2000 By T.L. Freeman, LS 21367  
Location filed: Certificate of Survey for Steffen, #1028  
Monument: GLO Brass Cap Monument found  
  
5/2002, T.L. Freeman, LS 21367  
Certificate of Survey for Lehmann, #1566  
GLO Brass Cap Monument found  
  
7/2011, B.W. Skipton, LS 17768  
Certificate of Survey for Segler, #4696  
Indicates found survey monument at corner.  
  
7/2019, CCHD/SO  
#2019.014  
Found GLO pipe, cap gone, top bent, replace with aluminum  
Cass Co. monument, down 0.4', 17'+/-, S. of centerline Co. Rd.  
#126, place GLO pipe adjacent on S. side of aluminum mon.  
20" Red Pine, S 20° E, 35.82'(1918) duplex nail, up 1.0', E. side  
14" Red Oak, N 2° E, 111.07'(2000) duplex nail, up 1.0', E. side  
18" Red Oak, S 62° E, 108.06'(2000)duplex nail, up 1.0', N. side  
13" Red Pine, N 20° W, 100.53'(2000)duplex nail, up 1.0', W. side

Index No. P 17

CASS COUNTY LAND CORNER RECORD

T. 14 R. 20 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 22 Corner common to sections 22, 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter NO TREES  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1918 By GLO  
Location filed SECRETARY OF STATE  
Monument NO ORIG. EVIDENCE - SET 1x36" I.P. W/BRASS  
CAP.  
14  
522 / 523  
1918

Evidence of Subsequent Corner Restoration

Year of search 8/03 By R. Mustonen  
Certificate of Survey indicates  
GLO Monument in place.

Bearing Trees, Reference Objects

Species ALPINE TAM.  
Diameter 10" 6"  
Bearing S 72 1/4 E S 33 1/2 W  
Distance 55 LKS 152 LKS

Bearing Trees, Reference Objects

P-17

Subsequent Corner Restoration

Year surveyed 6/2000 By CCSO  
Location filed file #99025  
Monument Replace GLO monument removed  
during Co. Rd #126 construction.  
witness as follows:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

13" N. Pine N 20° W 100.53' \*  
14" R. Oak N 2° E 111.07' \*  
18" R. Oak S 62° E 108.06' \*  
20" N. Pine S 20° E 35.82' \* (GLO)  
\*distance to double head nail

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_