


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

= Corner

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument: $1/4 \frac{S28}{S33}$
1918

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. V 11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 574 Coordinates: X _____ Y _____
N 1/4 33 Corner common to sections 28, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species W. PINE
Diameter 18"
Bearing N 70 E
Distance 104 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SECRETARY OF STATE
Monument 1X36" I.P. W/ BRASS CAP. PROPORTIONAL POSITION
NO ORIGINAL EVIDENCE 1/4 528
533
1918

Evidence of Subsequent Corner Restoration

Year of search 1983 April By Freeman - Hammit - Sch
Found brass cap and SE GLO B.T.
1962 Okerman B.T. 10" Oak N 5 1/2 E is gone
Found 7" Oak Blazed S 30 W 12.25' put
spike on NW side

Bearing Trees, Reference Objects

Species N. PINE B. OAK
Diameter 6" 8"
Bearing S 74 E N 38 1/2 W
Distance 56 LKS 20 LKS

Bearing Trees, Reference Objects

V-11

Subsequent Corner Restoration

Year surveyed 1968 By Co Hwy Dept
Location filed CORR # 5
Monument brass cap

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1962

1989 Certificate - David Landecker
Doc. # 311162.
Found 1" GLO iron monument with brass
cap. Ties: 7" Birch N 66 E 43.53'; 22"
Norway Pine S 74 E 37.37'; 10" Burr Oak
S 85 W 40.46'.

1992 - W. Curd - Certificate of
survey indicates iron monument
in place.

OCT. 1998
CCSO occupied GLO iron mon.
w/ brass cap

Sept. 2004 T. Freeman #21367
Cert. of Survey shows monument found (brass
cap)

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____