


T. 141 R. 20 M. 5TH Coordinates: X _____ Y _____
N 1/4 34 Corner common to sections 27, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument IN POND

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SECRETARY OF STATE
Monument SET W. C FOR 1/4 COR. S 87-46 E 3.48 CH.
SET 1x3/8" I.P. w/BRASS CAP w/1/4 527
534
1918

Evidence of Subsequent Corner Restoration

Year of search 1989 By David Landecker
Found 1" x 3/8" iron monument with brass
cap. Set 3/4" x 13' aluminum rod with
aluminum cap.

Bearing Trees, Reference Objects

Species SPRUCE W. PINE
Diameter 5" 15"
Bearing N 57 E S 40 1/4 E
Distance 69 LBS 115 LBS

Bearing Trees, Reference Objects

Burr Oak Norway Pine Maple White Pine
13" 25" 8" 32"
N 56 E N 81 E S 15 E S 40 E
159.70' 165.23' 173.32' 75.9'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Plat - Auditors Plat of Longville
George Claydon 1963
1989 Certificate - David Landecker
Doc. # 311943

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____