


Index No. 2 15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X _____ Y _____
S 1/4 34 Corner common to sections 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees
Species	<u>MARLE</u>	<u>W. BIRCH</u>
Diameter	<u>4"</u>	<u>6"</u>
Bearing	<u>N30W</u>	<u>N30E</u>
Distance	<u>9 LKS</u>	<u>9 LKS</u>

Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 1965 By Co. Hwy Dept.
Location filed Co. RD # 54
Monument Found 2" 1IP

Evidence of Subsequent Corner Restoration

Year of search 1927 By ?
microfilm - roll 115 BK 77 P. 122-123

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

<u>N. Pine</u>	<u>Pop.</u>
<u>10"</u>	<u>8"</u>
<u>S 79-35 W</u>	<u>S 29-12 W</u>
<u>31.8'</u>	<u>11.9'</u>

2-15

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - SOUTH LONGVILLE
JOHN W. CURR 1945

PLAT - HEINLEN'S SUB-DIVISION
W. J. SPAIN JR 1955

PLAT - AUDITORS PLAT OF LONGVILLE
GEORGE CLAYTON 1963

1989 Certificate - David Landecker
Doc # 315249

Found 1 3/4" iron pipe.
Set 2" x 48" iron pipe with brass cap
and plastic base with magnet. Ties: 25"
Norway Pine S 78 W 32.50'; 9" Birch
S 8 W 33.35'; 14" Red Oak S 28 E
47.30'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____