


Index No. 219

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S1/4 35 Corner common to sections 35



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1863

Original monument 6" W. PINE

Species	Bearing	Trees
<u>ASPEN</u>	<u>ASPEN</u>	
Diameter <u>7"</u>	<u>6"</u>	
Bearing <u>N46W</u>	<u>N42E</u>	
Distance <u>11 LKS.</u>	<u>5 LKS</u>	

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance

**Subsequent Corner Restoration**

Year surveyed 1953 By Co. Hwt Dept

Location filed Co Rd #7

Monument Found iron pin

**Evidence of Subsequent Corner Restoration**

Year of search 1989 By David Landecker

Set 2" x 24" iron pipe with brass cap.

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
<u>Norway Pine</u>	<u>10"</u>	<u>N 50 W</u>	<u>147.37'</u>
<u>Norway Pine</u>	<u>12"</u>	<u>N 20 W</u>	<u>108.21'</u>
<u>Jack Pine</u>	<u>14"</u>	<u>N 27 E</u>	<u>147.81'</u>

2-19

Subsequent Corner Restoration

Year surveyed Mar 2005 By CCSO

Location filed \_\_\_\_\_

Monument Found PK, strong magnetic reading  
2.5' SQF C, co. Rd. #7. Could  
not find nails in 1989 NW wit-  
ness trees.

- \* 10" N. Pine N24° W 108.11'
- \* 14" J. Pine NE 20d spike
- \* 10" N. Pine S10° W 44.53'
- \* - Dist near to dbl hd nail.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

1989 Certificate - David Landecker  
Doc. # 312360

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_