


Index No. E5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X 457997.57 Y 190533.18  
NE 7 Corner common to sections 3, 6, 7, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
 Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing	Tree	Distance
<u>Y. PINE</u>	<u>0AK</u>	<u>0AK</u>	
<u>16"</u>	<u>6"</u>	<u>10"</u>	
<u>N49E</u>	<u>N67W</u>	<u>S37E</u>	
<u>16 LKS</u>	<u>23 LKS</u>	<u>33 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1918 By GLO  
 Location filed SEC. OF STATE  
 Monument FIND DELAYED WOOD STAKE AND ALL 3 ORIG  
B.T. STUMPS - SET 2X36" 1/2" W/ BRASS CAP T141W R29W  
56/55  
57/58

Evidence of Subsequent Corner Restoration

Year of search 1938 By H. Sorenson MNDOT  
 Found battered iron pin, 2.3'  
S. of 9.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>R. OAK</u>	<u>16"</u>	<u>N40-15E</u>	<u>70 LKS</u>
<u>ROAK</u>	<u>8"</u>	<u>S25E</u>	<u>57 LKS</u>
<u>ROAK</u>	<u>8"</u>	<u>S51-15W</u>	<u>21 LKS</u>
<u>R. OAK</u>	<u>16"</u>	<u>N17-45W</u>	<u>71 LKS</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

E-5

Subsequent Corner Restoration

Year surveyed 1941 By MNDOT  
 Location filed MNDOT Baxter Office  
 Monument Iron monument and brass  
cap, near 9 old road, 104.9 S.  
of new Hwy #200.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BUTLER SMITH - HWY ENGINEER - 1921  
Found iron pipe with brass cap. Ties:  
15" Elm S19°15'E 36.5'; 15" Elm N36°  
15'E 42.2'.

9/1989 - AMI Surveyors - Found  
2" pipe, replace with Alum cap.  
4" Ash N59°W, 27.89  
6" Ash N16°E, 15.74  
7" Poplar S54°E, 27.84  
7" Maple S13°W, 52.34

MAR 2002 T. FREEMAN  
CERT of SUR SHOWS MON FOUND

9/03 - NLSEM - Found Alum cap  
tipped, straighten and lower to  
5" below old road bed. A CofL  
was filed.

<u>14" Oak</u>	<u>S22°W</u>	<u>49.30</u>
<u>8" Oak</u>	<u>N17°E</u>	<u>15.72</u>
<u>10" Poplar</u>	<u>S50°E</u>	<u>27.87</u>
<u>4" Oak</u>	<u>N40°E</u>	<u>42.55</u>
<u>9" Maple</u>	<u>S10°W</u>	<u>42.30</u>
<u>6" Oak</u>	<u>N57°W</u>	<u>27.85</u>

Remonumentation certificate prepared \*480067  
 Filed at CCRO

By \*16039  
 Date 2/12/04