


T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 8 Corner common to sections 8, 9



EXISTING SURVEYS

Original Government Survey
Year surveyed 1873
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species MAPLE Y. ANE
Diameter 4" 16"
Bearing N 23 W S 75 E
Distance 15 LKS 24 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1918 By GLO
Location filed SEC. OF STATE
Monument FND 5/5 X 40" WOOD STAKE W/ SCRIBING - SET
1 X 3/8" I.P. W/ BRASS CAP
ALSO FND SE BIT STUMP. 11/4
58/59
1918

Evidence of Subsequent Corner Restoration
Year of search 1980 By Gary STEVENSON
Found 1" iron pipe in road. Set 2" x 24"
galvanized iron pipe with marked brass
cap down 14" below road surface.

Bearing Trees, Reference Objects
Species W. OAK W. OAK
Diameter 16" 12"
Bearing S 70 E N 87-45 W
Distance 84 LKS 39 LKS

Bearing Trees, Reference Objects
W. Oak W. Oak W. Oak
9" 12" 21"
N 74 W S 59 W S 70 E
96.15' 60.34' 55.14
GLO

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____
Nov. 1914; Twp Rd order shows no survey

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981
Doc. # 260981