


T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
E11418 Corner common to sections 17,18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Species	Bearing	Trees
<u>BIRCH</u>	<u>OAK</u>	
Diameter <u>5"</u>	<u>7"</u>	
Bearing <u>S78E</u>	<u>S13W</u>	
Distance <u>21 LKS</u>	<u>33 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By JOHN CURO

Location filed COUNTY BOOK "C" P. 259

Monument FIND STAKE & 2 BOTS ABOUT 5 YRS OLD
1917 JOHN CURO, BOOK "C" P. 260 PULMON GOVT STAKE
SET 2x4 @ 7. M.
also on microfilm - roll 105 BK 56 P. 54, 61, 81

Species	Bearing	Reference Objects
<u>MAPLE</u>	<u>IRONWOOD</u>	
Diameter <u>8"</u>	<u>5"</u>	
Bearing <u>N65-45W</u>	<u>S58E</u>	
Distance <u>23.40'</u>	<u>3.05'</u>	

Evidence of Subsequent Corner Restoration

Year of search 1918 By GLO

FND 1 1/4" GALV. IIP. SET 1x36" IIP. W/BRASS CAP

114
S10/S17
1918

Species	Bearing	Reference Objects
<u>MAPLE</u>	<u>MAPLE</u>	
Diameter <u>10"</u>	<u>8"</u>	
Bearing <u>S60-45E</u>	<u>S81W</u>	
Distance <u>60 LKS</u>	<u>LKS</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER - 1963

Found GLO monument in good condition with
1 1/4" iron pipe alongside; 10" Maple S60°45'E
60 LKS now stump; 8" Maple S81W 71 LKS
now stump hole. New ties: 9" Maple S15E
28.5'; 7" Oak S79W 42.2'; 7" Oak N20W
61.65'.