


Index No. L-m 5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
MC Corner common to sections 18, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1x36" IR. W/BRASS CAP

Bearing Trees

Species	<u>N. PINE</u>	<u>POPLAR</u>	_____	_____
Diameter	<u>30"</u>	<u>8"</u>	_____	_____
Bearing	<u>N35E</u>	<u>N62-W</u>	_____	_____
Distance	<u>8 LKS</u>	<u>79 LKS</u>	_____	_____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1988 By David Landecker

found 1" iron pipe with brass cap.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Spruce</u>	<u>Red Oak</u>	<u>Norway Pine</u>	<u>Iron Pipe</u>
<u>13"</u>	<u>9"</u>	<u>27"</u>	<u>1 1/4"</u>
<u>N 40 W</u>	<u>N 10 W</u>	<u>N 35 E</u>	<u>N 5 W</u>
<u>75.49'</u>	<u>32.32'</u>	<u>5.92'</u>	<u>6.41'</u>
		<u>GLO</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1989 Certificate - David Landecker

Doc. # 310036

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____