


Index No. N 11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
N 1/4 21 Corner common to sections 16, 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Species	Bearing	Trees
<u>Y. PINE</u>	<u>Y. PINE</u>	
<u>20"</u>	<u>18"</u>	
<u>N39E</u>	<u>S34W</u>	
<u>32 LKS</u>	<u>35 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO

Location filed SEC. OF STATE

Monument 1x36" I.P. w/ BRASS CAP SET FROM STUMP OF NE B.T.

1/4 516
521
1918

Evidence of Subsequent Corner Restoration

Year of search 1988 By David Landecker

Found 1" iron pipe with brass cap.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>N PINE</u>	<u>5"</u>	<u>N89-30E</u>	<u>203 LKS</u>
<u>R. OAK</u>	<u>16"</u>	<u>N59-45E</u>	<u>196 LKS</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Red Oak</u>	<u>13"</u>	<u>N20E</u>	<u>67.71'</u>
<u>Norway Pine</u>	<u>23"</u>	<u>N60E</u>	<u>129.40'</u>
<u>Maple</u>	<u>5"</u>	<u>S74E</u>	<u>32.73'</u>
<u>Norway Pine</u>	<u>15"</u>	<u>S61W</u>	<u>43.35'</u>
<u>GLO BT</u>		<u>GLO BT</u>	<u>1980 BT</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - GARY STEVENSON - 1982
Doc. # 2103902

1989 Certificate - David Landecker
Doc. # 310666

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____