


Index No. T 25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E114 25 Corner common to sections 25 AND 30 - 141-28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species N. PINE  
Diameter 16"  
Bearing N70W  
Distance 19 LKS.

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO  
Location filed COUNTY SURVEY RECORD BOOK B P. 169-177  
Monument PULL HUB, SET 2 1/2 X 48" IRON W/ CAP  
also on micro film - roll 105 BK 60 P. 144

Evidence of Subsequent Corner Restoration

Year of search 1918 By GLO  
FOUND 2" I.P. - SET 1 X 36" I.P. W/ BRASS CAP  
5 25 1/4 530  
1918

Bearing Trees, Reference Objects

Species W. BIRCH  
Diameter 4"  
Bearing N 68W  
Distance 20.20'

Bearing Trees, Reference Objects

W-OAK R. OAK  
14" 4"  
S 73 3/4 E N 15 1/4 W  
209 LKS 41 LKS

Subsequent Corner Restoration

Year surveyed 1968 By Co Hwy Dept  
Location filed Co RD # 5  
Monument Found US 660 Corner

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL DEARMAN - 1965  
1989 Certificate - David Landecker  
Doc. # 311171  
Found GLO monument in good condition.  
TIES: 10" Red OAK N45W 46.08'; 7"  
NORWAY PINE S45W 46.34'; 12" Red  
OAK S56E 35.49'.

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_