


Index No. V 15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 14 34 Corner common to sections 27, 34



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing	Trees		
Species	<u>W. PINE</u>	<u>W. PINE</u>	_____	_____
Diameter	<u>20"</u>	<u>22"</u>	_____	_____
Bearing	<u>N 85 E</u>	<u>S 84 E</u>	_____	_____
Distance	<u>21 LKS.</u>	<u>23 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO  
Location filed SEC. OF STATE  
Monument FIND OLD WOOD POST AND BETA COAT BITS.  
SET 3x36" WOOD POST 16" IN GROUND

Evidence of Subsequent Corner Restoration

Year of search 1989 By David Landecker  
Set 2" x 48" iron pipe with brass cap  
and plastic base with magnet.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Burr Oak</u>	<u>Red Oak</u>	<u>Red Oak</u>
<u>6"</u>	<u>6"</u>	<u>10"</u>
<u>N 8 E</u>	<u>S 61 E</u>	<u>S 2 E</u>
<u>36.50'</u>	<u>46.91'</u>	<u>63.42'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1989 Certificate - David Landecker  
Doc. # 311851

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_