


Index No. Y-221

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 57a Coordinates: X _____ Y _____
Reference SE Corner common to sections 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1983 By Gary Stevenson
Location filed CORNER Certificate
Monument Set 2x36" galv. l.p. w/ 3" brass cap
on line betw. NE and corner position for SE
35
Corner is 206.61' South

Evidence of Subsequent Corner Restoration

Year of search 1988 By David Landecker
Found 2" iron pipe with brass cap.

Bearing Trees, Reference Objects

Species <u>Birch</u>	<u>w. oak</u>	_____
Diameter <u>8"</u>	<u>10"</u>	_____
Bearing <u>N26E</u>	<u>S62W</u>	_____
Distance <u>44.13'</u>	<u>26.36'</u>	_____

Bearing Trees, Reference Objects

<u>Birch</u>	<u>Birch</u>	<u>Birch</u>
<u>8"</u>	<u>9"</u>	<u>8"</u>
<u>North</u>	<u>N40E</u>	<u>S78W</u>
<u>58.33'</u>	<u>44.06'</u>	<u>58.98'</u>

(1983 BT)

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Gary Stevenson - filed by USES 1984
Doc. # 279158 dated 1983
1989 Certificate - David Landecker
Doc # 311178

Re monumentation certificate prepared _____ By _____
Filed at _____ Date _____