


T. 141 R. 29 M. 5th Coordinates: X _____ Y _____
SE 36 Corner common to sections 36 AND 31-141-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Species	Bearing	Trees
<u>Y. PINE</u>	<u>W. LINE</u>	
Diameter <u>20"</u>	<u>24"</u>	
Bearing <u>N17W</u>	<u>N16E</u>	
Distance <u>54 LKS</u>	<u>45 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By JOHN CURD

Location filed COUNTY SURVEY RECORD BOOK "A" P. 556-558

Monument FND OLD GALT B.T STUMPS 20" Y. PINE N17W 54 LKS, 24" W. PINE N16E 45 LKS. SET 2 1/2 X 8" GALV I.P. W/ 3" CAP AND 1/2" X 2" ROD AS ANCHOR

1915 - JOHN CURD BOOK "B" P. 169-177 FND IRON W/ CAP

Evidence of Subsequent Corner Restoration

Year of search 1918 By GLO

FND 2" I.P. AND BOTH B.T STUMPS

(SET NO NEW CORNER)

1912 - also on microfilm - roll 105 BK 69 P. 86-87

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
<u>B. PCH</u>	<u>TALL BIRCH STUMP</u>	
Diameter <u>3"</u>	<u>10'</u>	
Bearing <u>N25E</u>	<u>N85W</u>	
Distance <u>19.14</u>	<u>3.81'</u>	

TODD'S B.T'S

Bearing Trees, Reference Objects

1915 - also on microfilm - roll 115 BK 78 P. 8

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - BILL OKERMAN - 1965

1989 Certificate - David Landecker

Doc. # 311180

Found concrete monument with a brass cap and County capped monument.

Ties: 10" Maple N30W 48.25' (1965 BT);

9" Maple N24E 75.71' (1965 BT); 8"

Maple S48E 40.68'

Corner GPS ccsa 7/30/02

ccsa Fd. 2" O.D.I.P. 1 Cap, up 1.2'